

Incident: 93328 ▼[Options](#) ▼[Print](#)[Refresh](#)

Status: Complete

Short Description: noticed leakage from the rear man way/bulkhead on rented frac tank

Responsible Department: Peru Plant : EPS-Peru

Level of Consequence: INCIDENT

Subtypes

Incident Sub Types: General: Environmental

General

Supervisor: CHAPMAN, ADAM W

Location: Building 4

Specific Location/Equipment: Rented frac tank

Crew/Shift: Unknown

Date Occurred: 6/21/2014 2:30 PM

Date Reported: 6/21/2014 2:30 PM

Summary of Incident: While filling rented frac tank with water/foam/defoamer/styrene mixture, Barry Kelly noticed visual leakage from the rear man way/bulkhead. Estimated volume less than 10 gallons. All bulkhead/ man ways were tightened by Steve Emmett on tank. 50 lbs of absorbant clay mixture was placed on the spill and nearest storm water drain (approx. 60 yds away) was immediately surrounded with absorbant pads. All future frac tanks used on-site will have all connections/bulkheads tightened before filling with any liquids.

Weather: Overcast, Rain

Legal Hold?: N

Responsibilities

Supervisor: SHEA, MICHAEL